
Perfect Fit Template



WARNING: Do not solder copper pipe or PEX adapters in a manner that would allow flux or other corrosive chemicals to run down the pipe into or near the valve or box. Flux contains corrosive chemicals that can damage plastic & metal components. Do not allow flux, bleach, cleaners containing acid or any other corrosive chemicals come in contact with ACCOR® 4ALL®BOX products. ACCOR Technology, Inc. does not warrant any failure due to faulty installation or abuse, stress condition, excessive water hammer, over torque, damaged pipe, exposure to below freezing conditions, excessive heat and/or corrosive chemicals and/or other destructive materials.




4ALL®BOX


Installation Instructions

Between Studs


Straddling Stud



With Arresters



Without Arresters



TO CLOSE VALVE: PULL MANDLE

POUS ACRES

ACR

With Condensation



With Water Softner Funnel





With Air Admittance Valve



www.accortechnology.com RM# 768 · 1/18 v2

Determine Configuration of Boxes





0 0 0

- -Cut at inner ring to butt pipe against box.
- -Cut at outer ring to pass drain pipe into box.
- -To install funnel/AAV, install to drain pipe. (glue optional)